

návod je ilustrační - židle neobsahuje opěrný kruh na nohy

1	2	3	4	5	6	7	8
序号 sequence number	名称 designation	规格 specifications	数量 number				
a	1	五星脚 Base	Ø640	1			
	2	脚轮 Caster	50	5			
	3	气杆 Gas lift	200	1			
	4	吧圈 Footrest	Ø450	1			
	5	防尘套 Back barcover		1			
b	6	背铁 Back bar		1			
	7	底盘 Mechanism		1			
	8	椅座 PU Seat		1			
	9	椅背 PU Back		1			
c	10	椅背链接件 Back connection		1			

e	内六角螺栓 Hex socket head cap screw	M6X25	4	
d	胶垫 Rubber washer	Ø16X10	6	
c	平垫片 Flat washer	Ø6	6	
b	内六角螺栓 Hex socket head cap screw	M6X45	2	
a	六角扳手 Hex wrench	K5	1	
	序号 sequence number	名称 designation	规格 specifications	数量 number